



Three-phase motor for 3 speeds
 with 2 separate windings
 winding 1 in Dahlander connection for speed 1, 3

Conn. diagram
KP 0034



For pole-changing switch connect all terminals with pole-changing switch
 star connections for high speed by pole-changing switch

				Datum	24.09.2005
				Bearb	Kresse
				Gepr	
				Norm	
01					
Zust.	Mitteilung	Datum	Name		
				 Elektromotorenwerk Wernigerode	
				Zeichnungs-Nr. KP 0034 e	